



CyFlex® Release Notes

Release Version 7.0.23

Developed by TRP Laboratories

Table of Contents

Overview	1
Installation Notes	1
Issue Type and Jira Issue Legends.....	1
General Applications	1
Transient Emission Applications	2
Release Notes for Previous cyflex.6.3 and cyflex.7.0 Versions	2

Overview

This release notes document identifies and describes the updates for CyFlex version 7.0.23. The following link contains Jira issues within this release: [cyflex.7.0.23 - Jira Issues](#)

Refer to *Installation Notes* below for install-related considerations.

Installation Notes

CFBUG-3479 – see [mk_ecm_files12 usage](#) – the config_cal_path required argument has been added

Issue Type and Jira Issue Legends

Refer to the following legend for **Issue Type**:

Issue Type Key	Definition
NF	New feature
B	Bug
I	Improvement

X = denotes additional information about change within the **Related Jira Issue**.

General Applications

Application, Script, or Library	Install Note Above	Issue Type	Bug Fix Name	Description
floger		B	CFBUG-3481	Improved handling of reconfigs

Application, Script, or Library	Install Note Above	Issue Type	Bug Fix Name	Description
floger dlogger libloggershared.so		B	CFBUG-3484	Improvement to allocate more storage to handle longer intervals
limit_specs limit		B	CFBUG-3485	Fixed abort_limit being triggered on reruns of limit_specs
unico_modbus_srv		B	CFBUG-3486	Clean up legacy events for unico_modbus
floger dlogger libloggershared.so		B	CFBUG-3488	Prevent crash on re-read

Transient Emission Applications

Application, Script, or Library	Install Note Above	Issue Type	Bug Fix Name	Description
mk_ecm_files12	Y	B	CFBUG-3479	Add processing of NEW config_cal_path argument to fix core dump

[Release Notes for Previous cyflex.6.3 and cyflex.7.0 Versions](#)